



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
September 7, 2007

Supervisor DAZ

Mine Name: Mayfield Quarry
Operator Name: Phyllis Bown

Permit number: M0390011
Inspection Date: August 29, 2007
Time: 11:30 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: None
Mine Status: Site Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine inspection while in the area.

Inspection Summary:
Reclamation of this site (including seeding) was completed in the fall of 2006. During this inspection, the only vegetation that was noted on the areas seeded last fall was tumbleweed and annual kochia (seeded species were not observed). The area was stable with no signs of erosion.

Photos were taken to document site conditions.

Conclusions and Recommendations:
The operator may want to consider re-seeding this fall. Regardless, if seeded species are not observed next spring, the operator should then consider weed control during the late spring and summer, and reseed the fall of 2008.

Inspector's Signature [Signature]

LK:pb

O:\M039-Sanpete\S0390011-MayfieldQuarry\inspections\insp-08292007.doc